

SAFETY DEVICES

SAFETY DEVICES							
Date	Inspection No	Road name	Segment No	Chainage	Length	Comments	Priority
2/10/2012	I004398	Sandy Creek Road	RLSANDR050	4205-4560	355	RHS possible new guardrail	1
10/12/2012	IN04387	Bylong Valley Way	RLBYLOW160	16740-17600	860	Right - possible site for guardrail	1
10/12/2012	IN04387	Bylong Valley Way	RLBYLOW200	21275-21500	225	Right - possible site for guardrail - extend existing?	2
10/12/2012	IN04387	Bylong Valley Way	RLBYLOW200	21650-21750	100	Right - possible site for guardrail - extend existing?	2
10/12/2012	IN04387	Bylong Valley Way	RLBYLOW250	26900-27200	300	Right - possible site for guardrail	2
20/07/2017		Hebden Road	RLHEBDR060-070		390	LHS New Guardrail	1
20/07/2017		Hebden Road	RLHEBDR060-070		430	RHS New Guardrail	1
20/07/2017		Hebden Road	RLHEBDR060-070		85	RHS New Guardrail	1
20/07/2017		Hebden Road	RLHEBDR060-070		200	RHS New Guardrail	1
		Bylong Valley Way		8960	20	New guard Rails on both sides	1
		Bylong Valley Way		1395	150	LHS New Guardrail	1
		Bureen Road		7263	20	LHS New Guardrail	1
1/01/2022		Acacia Road	RMACACD010/20/30		15	Speed Humps	1
2/01/2022		Carl Street	RMCARLS052		15	RHS New Guardrail	1
3/01/2022		Sandy Creek Road	RLSANDR060	5400	20	LHS New Guardrail	1
		Yarrawa Road		CH. 1.5		Investigte installation of linemarking on crest and centre BB lane.	1
		Yarrawa Road		CH.4.4		Bridge to new section one. Install guideposts on either side of the road.	1
		Yarrawa Road		CH.9.3		Replace no confirming guardrail end termenal.	1
		Bylong Valley Way		37645	40	LHS New Guardrail	1
		Bylong Valley Way		31810	40	New guard Rails on both sides	1
		Bureen Road		11923	40	RHS New Guardrail	1
		Bureen Road		12565	40	LHS New Guardrail	1
		Bureen Road		12631	90	RHS New Guardrail	1
		Bureen Road		12642	30	LHS New Guardrail	1
		Bylong Valley Way		27950	20	New guard Rails on both sides	1
31/10/2012	IN04397	Rosemount Road	RLROSER070	6200-6300	100	Guardrail RHS	1
1/10/2014	IN04773	Rosemount Road	RLROSER080	7250-7670	120	Guardrail LHS	1
20/11/2019		Yarrawa Road	RLYARWR052	4490-4570	80	LHS New Guardrail just after Yarrawa Deviation Road	1
1/10/2014	IN04776	Rosemount Road	RLROSER110	10000-10600	600	Possible guardrail LHS	1/2
31/10/2012	IN04397	Rosemount Road	RLROSER110	9790-9870	80	Possible site for guardrail - 3m drop either side of major culvert.	1/2
8/11/2012	IN04402	Yarrawa Road	RLYARWR070	6480-6510	30	Possible guardrail LHS	1/2
8/11/2012	IN04402	Yarrawa Road	RLYARWR080	7000-7300	300	Possible guardrail RHS	1/2
10/12/2012	IN04387	Bylong Valley Way	RLBYLOW180	19000-19130	130	Right - possible site for guardrail	1/2